



# Problemen met het koppelingspedaal

A close-up photograph of a mechanical assembly, likely a gearbox. A metal shaft with a splined end is shown. A black double-headed arrow is superimposed on the shaft, pointing both towards and away from the housing, indicating axial movement or clearance. The shaft is surrounded by a housing with a visible seal or O-ring.

Neem altijd de aanwijzingen van de autofabrikant in acht.